Property Inspection Report Summary



1234 Demonstration Way Fort Lauderdale, FL 33304

Date of Inspection

July 16th, 2023 8:00 AM

Client

John and Jane Client (555) 555-5555

Client's Agent

Sheila McRealtor (800) 500-0504 Inspected By

Ron Swanson #ABC123

A1 Home Inspections (800) 500-0504

https://www.eneris.ca



This report is also available as an interactive online presentation. Please see the link below or scan the QR code with your phone's camera app.

https://ener.is/presentation/anbTwYyctiLsJQG3T1



List of Actionable Findings Please Read Full Report for Details

Repair or Replace				
#	Category	Item	Condition	
1	Exterior	Exterior Doors	Rotted, Rusted	
2	Plumbing	Bathroom Faucets 2	Leaking	

Monitor				
#	Category	Item	Condition	
1	Exterior	Exterior Wall Coverings	Missing Caulking, See Additional Notes	
2	Exterior	Trim / Fascia	Missing Caulking	
3	Exterior	Patios	Normal Settling Cracks	
4	Exterior	Driveways	Normal Settling Cracks	
5	Exterior	Garage	Settling Cracks	
6	Exterior	Garage Door	Missing Caulking	
7	Roofing	Inner Eaves / Gutters	Clogged	
8	HVAC	Cooling Systems	Manufactured in 2016, Not Level	
9	Plumbing	Kitchen Basins	Dry, Signs of previous leaks/spills	
10	Plumbing	Kitchen Faucets	Check Water Filter	
11	Plumbing	Shower Stalls 1	Missing Caulking	

Summary Please Read Full Report for Details

EXTERIOR

Exterior Wall Coverings

Section 1.1

Description • Block

Stucco

Condition

 Missing Caulking

 See Additional Notes

Location

· Whole home







Trim / Fascia Section 1.2

Description • Metal

Condition

 Missing Caulking

Location

· Whole home

Monitor

Monitor

Reset nails that have worked themselves out. Recommended.

Please see the corresponding section in the

report body for additional notes.

Caulk seams where there are gaps where the facia meets the soffit. Recommended.

Caulk seams where there are gaps where the facia meets the structure.







Patios

Section 1.4

Description • Concrete

Condition

 Normal **Settling Cracks** **Monitor**

Recommend filling cracks in patio slab. These are from normal settling.



Location





Driveways Section 1.7

Condition

Location

Description • Concrete

 Normal **Settling Cracks**

Front of Home

Monitor

There are predictable cracks in the driveway that would not necessarily need to be serviced.

Recommend filling the cracks to help prevent moisture intrusion under the slab.







PLUMBING

Kitchen Basins

Section 5.2

Condition

Description • Double Vanity

Dry

 Signs of previous leaks/spills **Monitor**

Signs of spills and previous leaks. Noted Tested dry.

The base is beginning the delaminate at the front.

Location

Kitchen







Shower Stalls 1 Section 5.8

Description • Tile Condition

 Missing Caulking

Location

 Master Bathroom

Monitor

Please see the corresponding section in the report body for additional notes.







Minor Issues Please Read Full Report for Details

EXTERIOR

Exterior Doors Section 1.3

Description • Mixed door

types

Rusted

Condition Rotted

Location

· Front of Home

Rear of Home

Right of Home







The side garage door is rotted and rusted. Repair

Garage Section 1.8

Description • Attached Condition

Location

· Settling Cracks

• Right of Home

Monitor

Repair or Replace

or replacement recommended.

Cracks in floor from settling. Recommend filling.

Recommend caulking seam behind water heater.








ROOFING

Inner Eaves / **Gutters** Section 2.2



Clogged

Monitor Clean gutters. Recommended.





HVAC

Cooling Systems Section 4.3

Description Condition

Location

- **Description** Evaporative
 - Manufactured in 2016
 - Not Level

• Right of Home

Monitor

The unit is not level. This puts extra wear on the fan motor. Recommend leveling.







PLUMBING

Bathroom Description • Stainless Steel Repair or Replace

Faucets 2 Condition • Leaking Faucet leaks at the handle. The seal is probably

Section 5.5 Condition • Leaking bad. Repair needed.







